For Style 4281W Assembly Instruction Sheet #IS-4281W


oole Required: Flathand screndirier, Philips screndirier, plies, who culturs, who shippers, electrical tape, safety glesses. With Seases: (1) GO Cardelathe Base Bute 40W Maximum(hot Indude). Withouted Aussesbly Tites: 10-20 minutes repeation: Identity and inspect oil prids believe beginning installation, Check package content list and diagrams below to be sure all parts are repeat. If any parts are missing or damaged, do not alternat to assemble, Install, or operate the Solure. Contact customer service for replacement.


Warnings and Cautions

Turn off electricity at circuit breaker or main fuse box before installation. Consuit a licensed electricisn if in doubt. These instructions are provided for your safety. It is very important you read them completely before installing the fidure. We strongly recommend that a licensed, professional electricism parform the installation.


Disconnect fixture from power source before replacing bufbs. Make sure bufbs are given sufficient time to cool before removal

Package Contents





A. Fit the ceiling canopy to Mounting Screwe (DD) and secure with Screw (AA). Note: The ceiling canopy should be snug against the ceiling and the Screw (AA). If not, adjust the length of the STEP 3 — Fit Ceiling Canopy to Crossber Assembly necrewing the Hex Nut founting Screws (DD) by crews (DD) in or out of the the ceiling canopy is e, remove the crew(AA) Calling Canop



2 of 2